



# CÂMARA MUNICIPAL DE ARARAQUARA

## INDICAÇÃO Nº 318/2024

Manutenção corretiva em hidrante localizado na Rua São Vicente de Paulo, confluência com a Av. Santa Cecília, no bairro Vila Xavier.

Indico ao senhor Prefeito Municipal a necessidade de entrar em entendimento com os setores competentes, no sentido de que se seja feito contato com o Corpo de Bombeiros para que seja realizada a manutenção corretiva em hidrante localizado na Rua São Vicente de Paulo, confluência com a Av. Santa Cecília, no bairro Vila Xavier.

Conforme verificado por este gabinete, o hidrante está inoperante por falta de manutenção. Há peças ausentes no equipamento. Visto que a região possui muita mata nativa e terrenos baldios sem manutenção, é necessário seu reparo para que em caso de necessidade, possa ser acessado para uso. Agradeço a atenção dispensada e fico ao aguardo das devidas providências.

Sala de Sessões “Plínio de Carvalho”, 23 de janeiro de 2024.

LUNA MEYER

PROTÓCOLO 817/2024 - 23/01/2024 14:21

A photograph of a red fire hydrant on a concrete sidewalk. The hydrant is the central focus, showing signs of wear and rust. To its right is a circular access hole in the concrete. The background is a plain, light-colored wall. The ground is a mix of concrete, dirt, and some small green plants. The lighting is bright, creating shadows on the sidewalk.

**LUNAMIEYER**  
2023 - TODOS OS DIREITOS RESERVADOS.