



CÂMARA MUNICIPAL DE ARARAQUARA

INDICAÇÃO Nº 4662/2022

Reparos e substituições de partes danificadas nos bancos de madeira na Praça do CECAP "Maria Valéria Galvão Medina", Av. Domingos Ferrari Junior, 265-301, CECAP.

Indico ao senhor Prefeito Municipal a necessidade de entrar em entendimento com os setores competentes, no sentido de que sejam realizadas reparos e substituições de partes danificadas nos bancos de madeira na Praça do CECAP "Maria Valéria Galvão Medina", Av. Domingos Ferrari Junior, 265-301, CECAP.

Conforme verificado por este gabinete, alguns bancos da praça estão inutilizáveis e outros com partes quebradas. Assim, para que os munícipes possam desfrutar do ambiente natural e da paisagem, tendo seus momentos de lazer, é necessária a substituição dos bancos já muito danificados e reparos nos que ainda podem ser reaproveitados.

Certa de sua atenção e devidas providências, agradeço.

Sala de Sessões "Plínio de Carvalho", 3 de outubro de 2022.

LUNA MEYER

A close-up photograph of a wooden bench. The wood is painted a vibrant green, but the paint is peeling and worn, revealing the natural brown wood underneath. A significant portion of the wood is broken and splintered, showing the internal grain. Two green circular fasteners are visible on the wood. The background is a blurred natural setting with brown earth and green foliage.

Praça do CECAP "Maria Valéria Galvão Medina"
REPAROS DE BANCOS DE MADEIRA

Araraquara - Setembro/2022

LUNAMEYER